


1. Ensure the polarity of the wire connections is correct ?
2. Ensure the insulator sleeve is fitted beneath the board ?
3. Connecting the wires reversed, will damage the printhead.

FUSE 20 AMP
(Part No. FUS 763022)



A4 REF SHEET Issue 1.dwg

ISSUE	2	DATE	01 JUN 2004	MOD No	N/A	REASON	N/A
MATERIAL	SEE NOTE ABOVE			TITLE	INSTALL 24 VOLT PRINthead BOARD		
FINISH	NONE			OPEN DATE EQUIPMENT LTD PART NO REF 762072			
DRAWN	CWP	CHECKED	SCALE				