



REFERENCE DRAWING

4. NPN SENSOR or VOLTAGE FREE CONTACT



NB. The above drawing is for a 24v DC sensor deriving it's power from the thermal power supply. When the sensor has it's own power supply, LEAVE OFF THE +24v CONNECTION.

3. PNP SENSOR or VOLTAGE FREE CONTACT



NB. The above drawing is for a 24v DC sensor deriving it's power from the thermal power supply. When the sensor has it's own power supply, LEAVE OFF THE 0v CONNECTION.

ISSUE	1	DATE	6 FEB 2002	TITLE	HS1 POWER SUPPLY, Sensor or Voltage Free Contact	
DRAWN	CC	CHECKED		SCALE	NONE	PART NO. REF 767027
				OPEN DATE EQUIPMENT LTD		