




POTENTIOMETER 5 Volt printer setting (Adjust Through Hole)

MAIN POWER BOARD Part No PSU 763065



FUSE 4 AMP (24 Volt Stepper Motors) Part No FUS 763024

FUSE 1.6 AMP (9 Volt Terminal Display) Part No FUS 763023

FUSE 1.6 AMP (5 Volt Printer Supply) Part No FUS 763023

A4 REF SHEET Issue 1.dwg

ISSUE	2	DATE	20 MAY 2004	MOD No	N/A	REASON	N/A
MATERIAL	SEE NOTE ABOVE			TITLE	53E POWER SUPPLY FRONT COVER REMOVED		
FINISH	NONE			DRAWN		CWP	CHECKED
SCALE		NONE		OPEN DATE EQUIPMENT LTD		PART NO	REF 767067